




**United States Air Force
15th Air Base Wing
Environmental Restoration Program**

SITE INSPECTION REPORT PIER DUMP SITE

**Bellows Air Force Station
Oahu, Hawaii**



Appendix F GPS Survey Results

Appendix F – GPS Survey Results

| Location | Northing | Easting |
|-----------------------|----------|---------|
| Temporary Micro-wells | | |
| MW-01 | 72009 | 597561 |
| MW-02 | 71992 | 597748 |
| MW-03 | 71798 | 597778 |
| MW-04 | 71970 | 597812 |
| MW-05 | 71785 | 597871 |
| MW-06 | 72069 | 597862 |
| | | |
| Test Pits | | |
| TP001 North | 71816 | 597703 |
| TP001 South | 71786 | 597706 |
| TP002 North | 71815 | 597770 |
| TP002 South | 71791 | 597762 |
| TP003 South | 71997 | 597796 |
| TP003 East | 72009 | 597801 |
| TP003 West | 72013 | 597786 |
| TP004 North | 72082 | 597838 |
| TP004 South | 72062 | 597828 |
| TP005 North | 71891 | 597824 |
| TP005 South | 71874 | 597821 |
| TP005B East | 71891 | 597861 |
| TP005B West | 71887 | 597821 |
| TP006 North | 72001 | 597733 |
| TP006 South | 71985 | 597745 |