

**TABLE ES-1****Site Inspection Fieldwork Tasks for AOCs 18, 20, and 21***Site Inspections at AOCs 18, 20, and 21, Bellows AFS, Oahu, Hawaii*

Area of Concern (AOC)	Vegetation Clearing*	Geophysical Survey*	Surface Soil Sampling	Subsurface Soil Sampling	Trench Excavation	Groundwater Sampling
AOC 18 (World War II Landfill)	X	X	X	X	X	X
AOC 20 (Former Base Motor Pool Buildings 283 and 285)	X		X	X		X
AOC 21 (Former "Decon" Building 470)	X		X	X		X

**Notes:**

\*Task completed